

May 1, 2006

The following revision are issued as Development Manual Letter No. 2, 2006:

Section 7-02	Revised Subsections 7-02.9(9)(i) Lump Sum Estimates, Subsection 7-02.9(9)(j) Actual Cost Estimates and Subsection 7-02.9(10) Confidentiality and Payment in accordance with current MoDOT auditing procedures.
Figure 8-03.9	The Example Cross Sections (Box Truss – Cantilever and Butterfly) have been updated to correspond to Standard Plan 903.12. The example currently contained in the D-32 Microstation file will be removed.
Figure 8-03.17	The Column Design Table for Butterfly Trusses has been revised to correspond to Standard Plan 903.12. The table currently contained in the D-32 Microstation file will be removed.